

<http://www.dhv.de/db1/source/technicdatareportnotes.php?lang=en&item=213>

## **SAFETY NOTE HANGGLIDER HARNESS**


### **TENAX DHV 03-0111-00**

**Date** 13.11.2013

**Subject** Hangglider harness Tenax DHV 03-0111-00

In some single cases, the dimension of the reserve parachute handle is a bit too small for fixation at the harness. The handle is then not safely fixed, because the side ends can slip out on their own accord. Woody Valley recommends all owners of the Tenax 3 harness, to check the handle and fixation at the harness. The side ends of the handle should stick safely in the fixation. If the handle is too loose in the fixation, Woody Valley recommends affected owners replacing the handle. Woody Valley offers a proper handle for free.

All Tenax 3 harnesses, which have been manufactured since the middle of 2012, are equipped with the new handle. To be sure you can compare your handle to the attached photo:



Concerned owners are asked to contact the manufacturer or the national importer.

WOODY VALLEY s.r.l.  
VIA VIENNA, 92 - Loc. Spini, Sett. "D"  
38121 TRENTO - ITALY  
c.f./P.I. IT01249560226  
Tel +39 0461 950811  
Fax +39 0461 950819  
[www.woodyvalley.com](http://www.woodyvalley.com)  
[info@woodyvalley.com](mailto:info@woodyvalley.com)

---