



FRONT CONTAINER RESCUE HANDLE RECALL

Published on:

10 Jul 2025

IMPORTANT SAFETY NOTICE

Lite, Lite PPG and Cockpit Rescue Containers

We have detected a manufacturing defect over one rescue handle delivered together with a reserve container. The following reserve containers produced between Jan 1st, 2021 and June 16th, 2025 might be concerned:

Lite Rescue Container

Lite Rescue Container PPG

Cockpit Rescue Container



As a precaution, we ask that all container handles produced during this period be immediately taken out of use. The handles must be replaced before next use.

Please contact the retailer from whom you purchased your container to receive a free replacement handle after returning your handle, which will be destroyed.

The default affects the connection from the handle to container lanyard. This defect could result in the handle connection breaking before the reserve is fully deployed.

The replacement handles have a visible box-stitch pattern, as shown below.



For any questions, please contact your [local OZONE Dealer](#) or [Contact us](#) directly.



PRODUCTS

Paragliding Wings
Paramotor Wings
Speed Wings
Reserves
Harnesses

INFO

Technical Downloads
Warranty
Safety Notices
Repairs
Custom Wings

OZONE

Ozone Team
Contact Us
Find a Dealer
Product Registration
Nature
Ozone Kites

© 2025 OZONE PARAGLIDERS LTD. ALL RIGHTS RESERVED