## SAFETY NOTICE

Reserve handle check is required for PROGRESS 3 & EASINESS 2 harnesses

This notice applies to PROGRESS 3 harnesses with serial numbers lower than 1147390, and EASINESS 2 harnesses with serial numbers lower than 1147140. The reserve handle must immediately be inspected by pilots of these harnesses. The serial number of the harnesses can Be found on the back of the logo label next to the carrying handle on top of the rucksack. If this inspection is not satisfactory it is essential that the reserve handle and reserve container be changed before the next flight. Replacements will be provided by ADVANCE free of charge.

The reason for this notice is an incident with a PROGRESS 3 harness. When the reserve handle was pulled the yellow plastic release splint came away from the handle, so that the reserve parachute could not be released. In this case the pilot was, fortunately, not injured.

Initial internal investigations have shown that the attachment of the cable to the handle may have a defect which could be related to manufacturing procedure. Other harness models are not affected by this. Other PROGRESS 3 and EASINESS 2 harnesses (with serial numbers greater than the serial numbers above) are expressly not affected either, as from July 2018 the release handle in question was manufactured with different material and different processing.

As it cannot be ruled out with certainty that this is an isolated case, ADVANCE is launching a precautionary recall of all reserve parachute handles and reserve parachute containers on EASINESS 2 (serial numbers less than 1147140) and PROGRESS 3 (serial numbers less than 1147390) harnesses where the split pin cable cannot withstand a load of approx. 10-12 kg. Below we provide instructions for a simple test to determine whether the reserve parachute handle can withstand this required deployment force.

If the test is not satisfactory and the reserve parachute handle is affected, a new handle including container can be ordered free of charge at <a href="https://www.advance.swiss/en/recall/progress3\_easiness2">www.advance.swiss/en/recall/progress3\_easiness2</a>.

We apologise to all affected PROGRESS 3/EASINESS 2 customers for any inconvenience caused by this safety notice. Reliable equipment and high quality workmanship have been ADVANCE's top priority for over 30 years. We continue to focus on the highest quality product and its assurance, and will continue to improve this continuously.

**Download PDF** 

## **TEST INSTRUCTIONS**

## Instructions for the PROGRESS 3 and EASINESS 2 reseinandle check For PROGRESS 3 harnesses with a serial number lower than 1147390 and EASINI lower than 1147140. Carry out the check on your reserve parachute handle acco Tools required • (Disposable) rubber gloves to prevent the cable from slipping out of your ha • Weight 10-12 kg, e.g., a rucksack or bag filled with weight in the form of 1 s other tenss. • Line and possibly a carabiner to attach the weight. • Reserve handle incl. inner container. Preparation 1. Pull the reserve parachute out of its inner container. 2. Taske the reserve parachute out of its inner container. 3. Attach the weight 10-12 kg to the reserve handle by a carabiner analor inne. 4. Put an allow so that the yellow cable does not sallo out of your hand, graso it on one side of the handle and lift it until the entire weight is lifted from the ground.

## IS MY HARNESS AFFECTED?

You can check the serial number of your EASINESS 2 or PROGRESS 3 in the form. If your harness is affected and the reserve parachute handle test is negative, you can order a new handle with inner container free of charge here.

CHECK & ORDER

NEWSLETTER	PRODUCTS	SERVICES	ABOUT US	LANGUAGE
DO YOU WANT TO	Paragliders	Downloads	Brand story	Deutsch
STAY UP	Harnesses	Warranty extension	Team Pilots	<u>English</u>
TO DATE?	Reserves	Support	Contact	Francais
	Bags	Paraglider check	Imprint	
Subscribe to our	Clothing	Security	Privacy statement	

© Advance 2024

newsletter

YOUR E-MAIL ADDRI

SUBSCRIBE

Accessories