

## Serviceordre - Materiell

Materiellsjef F/NLF kommuniserer pålegg omkring forhold som ansees som vesentlige for å oppnå de målsettinger som er satt for materiellarbeidet via denne Service ordre. Målgruppen for Serviceordre er Materiellkontrollører, Hovedinstruktører og andre nøkkelpersoner i miljøet.

## SERVICEORDRE – 2010-1

**HENVISNING:** IPC S&T # 2/2010 og FFdF safety circular no 181, JMD/0212,

19 april 2010

**FORMÅL:** Sjekk av kutter på ARGUS AAD.

STATUS: Obligatorisk og før neste hopp

**IDENTIFIKASJON:** Alle nødåpnere av typen ARGUS.

**BAKGRUNN:** Det har vært en fallskjermulykke i Polen der ARGUS nødåpner

ikke kuttet korrekt og førte til en fatal ulykke.

**SERVICE:** Alle rigger som har ARGUS nødåpnere skal kontrolleres mht

produksjons dato. Dersom kutteren er merket med "JAN 2007" skal kutteren avmonteres og returneres til fabrikanten for å få ny

i retur. Se vedlagte IPC S&T varsel # 2/2010.

**UTFØRELSE:** Utføres før neste hopp og utføres av MK eller MR.

**DISTRIBUSJON:** Klubber

Hovedinstruktører Materiellkontrollører

SU

Spot on

Sky Design verksted F/NLFs Internet sider Hærens Jegerkommando

Luftfartstilsynet

Oslo, 12. Juli 2010

Rolf I Sotberg materiellsjef F/NLF

## **TECHNICAL & SAFETY COMMITTEE**





Technical & Safety Information Notice No.	02/2010 W.N. 29
Date of Issue	30 June 2010
Subject Matter and Applicability	FEDERATION FRANCAISE DE PARACHUTISME SAFETY CIRCULAR No. 181 Ref. JMD/0712 Issued 19 APRIL 2010
	SUBJECT: Recall of ARGUS cutters from the batch identified "JAN 2007".  EQUIPMENT REFERENCE: Argus SIS manufactured between January 2007 and October 2007.  BACKGROUND: Following a fatality in Poland, from the provisional report made by the authorities and from documents in our possession, it would appear that:  The student did not activate either the main or the reserve parachute  The Argus fired but  The cutter did not completely cut the reserve loop  That the loop broke on impact  ACTIONS: Immediate application of the recommendations indicated in a communication from the Manufacturer (see below). Immediate return of all cutters corresponding to the batch identified "JAN 2007".  QUALIFIED PERSONNEL: Drop Zone Technical Directors, Riggers, Tandem Instructors.
	AVIACOM SA  Wavre, April 8 <sup>th</sup> 2010  Following an incident that is currently under investigation and in an agreement between AVIACOM and the French Parachute Federation, AVIACOM SA requests that people using an ARGUS SIS to control the date of manufacture of it's cutter and if the batch is identified "JAN 2007", to return it for an exchange.
	AVIACOM indicates that 5% of each batch of cutters is tested for reliability and that, for the moment, nothing confirms any failure amongst them.  Equipment concerned: ARGUS SIS manufactured between January 2007 and October 2007  Procedure: visual check of the date of manufacture of the cutter Removal for exchange if the indication "JAN 2007" is observed.

Compliance	Immediate and mandatory implementation before the next jump.
Concerned Publication	Safety Circular No. 181, Ref JMD/0712, dated April 19 <sup>th</sup> 2010, Federation Francaise de Parachutisme  Communication from AVIACOM SA, Wavre, dated April 8 <sup>th</sup> 2010.
Authority	FFP and AVIACOM SA
	Ciam Mc Kulty IPC Technical & Safety Committee 30 June 2010

Technical and Safety Information Notices issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as information and help to parachuting nations and their affiliated members. The Information Notices are of an objective informative nature and there is no direct or implied criticism of any manufacturer or product intended. The Information Notices do not claim to be complete.

The Information Notices may result from:-

- 1 An incident or experience in the field being reported.
- 2 A directive or notice issued by an aviation or government authority concerning parachuting operations or parachuting equipment.
- The issue of a notice by a manufacturer or by a National Parachuting Organisation.

  In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this Information Notice. The reader assumes all liability.

The Technical & Safety Committee, International Parachuting Commission, can be contacted on e-mail - <a href="mailto:lmcnulty@skydiveireland.ie">lmcnulty@skydiveireland.ie</a>

Liam McNulty, Technical & Safety Committee, International Parachuting Commission. 30 June 2010